

News Number: YASN2015-001-A_SA221/324/424_SAFETY IMPORTANT NOTICE

SUBJECT: Unintentional PTO engagement with PTO switch saturated

Effective Date: June 4, 2015

Dear valued Yanmar customers and dealerships

At Yanmar America Corporation, we are committed to building high quality and a community of satisfied customers. We sincerely apologize for any inconvenience.

AFFECTED MODEL(S): SA221, 324, 424

For impacted units shipped from Yanmar America before June 4th 2015

A serial number list will be provided to each dealership individually from Yanmar America

Situation

In the current electric PTO circuit, if the PTO (Power Take Off) switch is saturated or wet, there is a risk of unintentional PTO engagement when PTO switch is OFF position.

Information

Please take caution when the PTO switch becomes saturated or wet until Yanmar supplies a solution.

A corrective PIP (product improvement program) notification will be issued soon and you will be immediately notified.

The repair kit will be available to order for each dealer no earlier than June 22nd 2015.



Sincerely yours,
Liston Edge
Senior Service Manager, Customer Support Department
Yanmar America Corporation

Yanmar America Corporation
Tel: 1-855-416-7091
e-mail: cs_support@yanmar.com